

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




Fig. 1




Fig. 2




Fig. 3






Fig. 4

BEST AVAILABLE COPY








Fig. 7




Fig. 8




Fig. 9




Fig. 10




Fig. 11





Fig. 12






Fig. 14




Fig. 15




Fig. 16




Fig. 17




Fig. 18




Fig. 19




Fig. 20




Fig. 21




Fig. 22





Fig. 23




Fig. 24




Fig. 25

2602	2604	2608	2610	2612	2614	2618	2620
Light System	Time	Position	Lit Position	Color Range	Intensity	Other Sys.	Position
LS001	T1	(1, 3, 7)	Poly001	0-16000	0-100		
LS001	T2	(1, 3, 7)	Poly001	0-16000			
LS001	T3	(1, 3, 7)	Poly 002	0-16000			
LS002	T1	(0,0,0)	Poly 003	0-16000			
LS002	T2	(0,0,0)	Poly004	0-16000			
LS002	T3	(0,0,0)	Poly 005	0-16000			
LS00N	TN						

Fig. 26




Fig. 27




Fig. 28




Fig. 29




Fig. 30




Fig. 31




Fig. 32




Fig. 33




Fig. 34




Fig. 35




Fig. 36




Fig. 37




Fig. 38




Fig. 39




Fig. 40




Fig. 41




Fig. 42




Fig. 43




Fig. 44




Fig. 45

Snap-in Bottom Mount




Fig. 46




Fig. 47




Fig. 48




Fig. 49




Fig. 50




Fig. 51




Fig. 52




Fig. 53




Fig. 54




Fig. 55




Fig. 56




Fig. 57




Fig. 58

5902




Fig. 59

6000




Fig. 60




Fig. 61




Fig. 62




Fig. 63




Fig. 64




Fig. 65




Fig. 66




Fig. 67




Fig. 68

Fig. 69a





Fig. 69b






Fig. 71